

STANDARD	EFFECTIVE DATE	INACTIVE DATE	REQUIREMENT	RESPONSIBILITY NOTES
BAL-001-2	7/1/2016		R1.	
BAL-001-2	7/1/2016		R2.	
BAL-002-2(i)	1/1/2018		R1.	MISO has whole responsibilities for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.3.1, and 1.3.2)
BAL-002-2(i)	1/1/2018		R2.	MISO has whole responsibilities for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.3.1, and 1.3.2)
BAL-003-1.1	11/13/2015		R1.	
BAL-003-1.1	11/13/2015		R2.	
BAL-003-1.1	11/13/2015		R3.	MISO has whole responsibilities for R3 and all sub-requirements (3.1 and 3.2)
BAL-003-1.1	11/13/2015		R4.	
BAL-005-1	1/1/2019		R1.	
BAL-005-1	1/1/2019		R2.	
BAL-005-1	1/1/2019		R3.	MISO has whole responsibilities for R3 and all sub-requirements (3.1 and 3.2)
BAL-005-1	1/1/2019		R4.	
BAL-005-1	1/1/2019		R5.	
BAL-005-1	1/1/2019		R6.	
BAL-005-1	1/1/2019		R7.	Each LBA with interconnection points with adjacent BAs of the MISO BA Area are responsible to ensure that common source equipment is installed where each Tie-line, Pseudo-Ties and Dynamic Schedule are implemented between that LBA and one or more neighboring Balancing Authorities external to the MISO BA Area.
CIP-002-5.1a	12/27/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, and 1.3)
CIP-002-5.1a	12/27/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1 and 2.2)
CIP-003-6	7/1/2016	12/31/2019	R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.1.1, 1.1.2, 1.1.3, 1.1.4, 1.1.5, 1.1.6, 1.1.7, 1.1.8, 1.1.9, 1.2, 1.2.1, 1.2.2, 1.2.3, and 1.2.4)
CIP-003-6	7/1/2016	12/31/2019	R2.	The MISO BA and the LBAs will be responsible individually for this requirement.
CIP-003-6	7/1/2016	12/31/2019	R3.	The MISO BA and the LBAs will be responsible individually for this requirement.
CIP-003-6	7/1/2016	12/31/2019	R4.	The MISO BA and the LBAs will be responsible individually for this requirement.
CIP-004-6	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1)
CIP-004-6	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.1.1, 2.1.2, 2.1.3, 2.1.4, 2.1.5, 2.1.6, 2.1.7, 2.1.8, 2.1.9, 2.2, and 2.3)
CIP-004-6	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1, 3.2, 3.2.1, 3.2.2, 3.3, 3.4, and 3.5)

STANDARD	EFFECTIVE DATE	INACTIVE DATE	REQUIREMENT	RESPONSIBILITY NOTES
CIP-004-6	7/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for R4 and all sub-requirements (4.1, 4.1.1, 4.1.2, 4.1.3, 4.2, 4.3, and 4.4)
CIP-004-6	7/1/2016		R5.	The MISO BA and the LBAs will be responsible individually for R5 and all sub-requirements (5.1, 5.2, 5.3, 5.4, and 5.5)
CIP-005-5	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.4, and 1.5)
CIP-005-5	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.2, and 2.3)
CIP-006-6	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.4, 1.5, 1.6, 1.7, 1.8, 1.9, and 1.10)
CIP-006-6	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.2, and 2.3)
CIP-006-6	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1)
CIP-007-6	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1 and 1.2)
CIP-007-6	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.2, 2.3, and 2.4)
CIP-007-6	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1, 3.2, and 3.3)
CIP-007-6	7/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for R4 and all sub-requirements (4.1, 4.1.1, 4.1.2, 4.1.3, 4.2, 4.2.1, 4.2.2, 4.3, and 4.4)
CIP-007-6	7/1/2016		R5.	The MISO BA and the LBAs will be responsible individually for R5 and all sub-requirements (5.1, 5.2, 5.3, 5.4, 5.5, 5.5.1, 5.5.2, 5.6, and 5.7)
CIP-008-5	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.3, and 1.4)
CIP-008-5	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.2, and 2.3)
CIP-008-5	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (3.1, 3.1.1, 3.1.2, 3.1.3, 3.2, 3.2.1, and 3.2.2)
CIP-009-6	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.4, and 1.5)
CIP-009-6	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1, 2.2, and 2.3)

STANDARD	EFFECTIVE DATE	INACTIVE DATE	REQUIREMENT	RESPONSIBILITY NOTES
CIP-009-6	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1, 3.1.1, 3.1.2, 3.1.3, 3.2, 3.2.1, and 3.2.2)
CIP-010-2	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.1.1, 1.1.2, 1.1.3, 1.1.4, 1.1.5, 1.2, 1.3, 1.4, 1.4.1, 1.4.2, 1.4.3, 1.5, 1.5.1, and 1.5.2)
CIP-010-2	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1)
CIP-010-2	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1, 3.2, 3.2.1, 3.2.2, 3.3, and 3.4)
CIP-010-2	7/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for this requirement.
CIP-011-2	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1 and 1.2)
CIP-011-2	7/1/2016		R2.	The MISO BA and the LBAs will be responsible individually for R2 and all sub-requirements (2.1 and 2.2)
COM-001-3	10/1/2017		R10.	
COM-001-3	10/1/2017		R12.	
COM-001-3	10/1/2017		R5.	The MISO BA will be responsible for R5.1, R5.2, and R5.5. The LBAs will be individually responsible for R5.3. The MISO BA and LBAs will be individually responsible for R5.4.
COM-001-3	10/1/2017		R6.	MISO has whole responsibilities for R6 and all sub-requirements (6.1, 6.2, and 6.3)
COM-001-3	10/1/2017		R9.	
COM-002-4	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.4, 1.5, and 1.6)
COM-002-4	7/1/2016		R2.	
COM-002-4	7/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for R4 and all sub-requirements (4.1 and 4.2)
COM-002-4	7/1/2016		R5.	
COM-002-4	7/1/2016		R6.	
COM-002-4	7/1/2016		R7.	
EOP-004-3	4/1/2017	3/31/2019	R1.	
EOP-004-3	4/1/2017	3/31/2019	R2.	
EOP-004-3	4/1/2017	3/31/2019	R3.	
EOP-008-1	7/1/2013	3/31/2019	R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.2, 1.2.1, 1.2.2, 1.2.3, 1.2.4, 1.2.5, 1.3, 1.4, 1.5, 1.6, 1.6.1, 1.6.2, and 1.6.3)
EOP-008-1	7/1/2013	3/31/2019	R2.	
EOP-008-1	7/1/2013	3/31/2019	R4.	
EOP-008-1	7/1/2013	3/31/2019	R5.	The MISO BA and the LBAs will be responsible individually for R5 and all sub-requirements (5.1)
EOP-008-1	7/1/2013	3/31/2019	R6.	

STANDARD	EFFECTIVE DATE	INACTIVE DATE	REQUIREMENT	RESPONSIBILITY NOTES
EOP-008-1	7/1/2013	3/31/2019	R7.	The MISO BA and the LBAs will be responsible individually for R7 and all sub-requirements (7.1 and 7.2)
EOP-008-1	7/1/2013	3/31/2019	R8.	
EOP-011-1	4/1/2017		R2.	The MISO BA and the LBAs will be responsible individually for R2 and sub-requirements 2.1, 2.2, 2.2.4, 2.2.5, 2.2.6, 2.2.7, and 2.2.8. The assignment of LBA responsibility among MECS, DECO, and CONS is further clarified under the Michigan Agreement and is reflected in the CFR submission. The MISO BA is fully responsible for sub-requirements 2.2.1, 2.2.2, 2.2.3, 2.2.3.1, 2.2.3.2, 2.2.3.3, 2.2.3.4.
EOP-011-1	4/1/2017		R4.	
INT-004-3.1	11/26/2014		R3.	
INT-006-4	10/1/2014		R1.	MISO has whole responsibilities for R1 and all sub-requirements (1.1 and 1.2)
INT-006-4	10/1/2014		R3.	MISO has whole responsibilities for R3 and all sub-requirements (3.1)
INT-006-4	10/1/2014		R4.	
INT-006-4	10/1/2014		R5.	MISO has whole responsibilities for R5 and all sub-requirements (5.1, 5.2, 5.3, 5.4 and 5.4)
INT-009-2.1	11/26/2014		R1.	MISO has whole responsibilities for R1 and all sub-requirements (1.1 and 1.2)
INT-009-2.1	11/26/2014		R2.	LBAs with Pseudo-Ties with external BAs shall be responsible for using dynamic values emanating from an agreed upon common source. The MISO BA (MBA) shall use the dynamic values for use in the Actual Net Interchange (NIA) term in their control ACE (or alternate control process).
INT-009-2.1	11/26/2014		R3.	
INT-010-2.1	11/26/2014		R1.	
INT-010-2.1	11/26/2014		R2.	
INT-010-2.1	11/26/2014		R3.	
IRO-001-4	4/1/2017		R2.	
IRO-001-4	4/1/2017		R3.	
IRO-006-5	7/1/2011		R1.	
IRO-010-2	1/1/2017		R3.	MISO has whole responsibilities for R3 and all sub-requirements (3.1, 3.2 and 3.3)
IRO-017-1	4/1/2017		R2.	
MOD-004-1	4/1/2011		R10.	
MOD-004-1	4/1/2011		R11.	
MOD-031-2	10/1/2016		R1.	MISO has whole responsibilities for R1 and all sub-requirements (1.1, 1.2, 1.3, 1.3.1, 1.3.2, 1.3.2.1, 1.3.3, 1.3.4, 1.4, 1.4.1, 1.4.2, 1.4.3, 1.4.4, 1.4.5, 1.5, 1.5.1, 1.5.2, 1.5.3, 1.5.4, and 1.5.5)
MOD-031-2	10/1/2016		R2.	
MOD-031-2	10/1/2016		R3.	
MOD-031-2	10/1/2016		R4.	MISO has whole responsibilities for R4 and all sub-requirements (4.1)
MOD-032-1	7/1/2015		R2.	
MOD-032-1	7/1/2015		R3.	MISO has whole responsibilities for R3 and all sub-requirements (3.1 and 3.2)

STANDARD	EFFECTIVE DATE	INACTIVE DATE	REQUIREMENT	RESPONSIBILITY NOTES
NUC-001-3	1/1/2016		R2.	
NUC-001-3	1/1/2016		R3.	
NUC-001-3	1/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for R4 and all sub-requirements (4.1, 4.2, and 4.3)
NUC-001-3	1/1/2016		R6.	
NUC-001-3	1/1/2016		R8.	
NUC-001-3	1/1/2016		R9.	The MISO BA and the LBAs will be responsible individually for R9 and all sub-requirements (9.2, 9.2.1, 9.2.2, 9.2.3, 9.3, 9.3.1, 9.3.2, 9.3.3, 9.3.4, 9.3.5, 9.3.6, 9.3.7, 9.4, 9.4.1, 9.4.2, 9.4.3, 9.4.4, and 9.4.5)
PER-003-1	10/1/2012		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1, 3.1.1, 3.1.2, 3.1.3, 3.1.4, and 3.2)
PER-005-2	7/1/2016		R1.	The MISO BA and the LBAs will be responsible individually for R1 and all sub-requirements (1.1, 1.1.1, 1.2, 1.3, and 1.4)
PER-005-2	7/1/2016		R3.	The MISO BA and the LBAs will be responsible individually for R3 and all sub-requirements (3.1)
PER-005-2	7/1/2016		R4.	The MISO BA and the LBAs will be responsible individually for R4 and all sub-requirements (4.1)
PER-005-2	7/1/2016		R5.	MISO has whole responsibilities for R5 and all sub-requirements (5.1)
PRC-001-1.1(ii)	5/29/2015	9/30/2020	R1.	
TOP-001-4	7/1/2018		R11.	
TOP-001-4	7/1/2018		R17.	
TOP-001-4	7/1/2018		R2.	
TOP-001-4	7/1/2018		R22.	
TOP-001-4	7/1/2018		R23.	
TOP-001-4	7/1/2018		R24.	
TOP-001-4	7/1/2018		R3.	
TOP-001-4	7/1/2018		R4.	
TOP-001-4	7/1/2018		R9.	
TOP-002-4	4/1/2017		R4.	MISO has whole responsibilities for R4 and all sub-requirements (4.1, 4.2, 4.3, and 4.4)
TOP-002-4	4/1/2017		R5.	
TOP-002-4	4/1/2017		R7.	
TOP-003-3	1/1/2017		R2.	MISO has whole responsibilities for R2 and all sub-requirements (2.1, 2.2, 2.3, and 2.4)
TOP-003-3	1/1/2017		R4.	
TOP-003-3	1/1/2017		R5.	MISO has whole responsibilities for R5 and all sub-requirements (5.1, 5.2, and 5.3)
TOP-010-1(i)	4/1/2018		R2.	MISO has whole responsibilities for R2 and all sub-requirements (2.1, 2.2, and 2.3)
TOP-010-1(i)	4/1/2018		R4.	